


X:\Clients\Augusta - Closed Project MPO and FS\Augusta Resource - Reclamation\5.0 Reports-Deliverables\5.2 Final Reports\Figures (Cadd)\REVISION C\FIGURE 30.dwg SAVED: 1/31/08 PRINTED: 3/11/08 BY: LENOVO USER



Prepared by: <b>M3</b> Engineering & Technology Corp. Tucson, Arizona Tel.(520)293-1488 Fax.(520)293-8349 Hermosillo, Sonora Mexico Tel. 011-52-622-2105400 Fax. 011-52-622-2105404		Issued by:  <b>TETRA TECH</b> 3031 West Ina Road Tucson, Arizona 85741 (520) 297-7723 (520) 297-7724 fax		<b>RECLAMATION AND CLOSURE PLAN POST-MINING FACILITY RENDERED VIEW W/ RELIEF FROM MILEPOST 46</b>		 REVISION
Project: ROSEMONT COPPER		Project no.: 320614		Figure no.: <b>30</b>		
Location: PIMA COUNTY, ARIZONA		Date: 01/08				