



X:\Clients\Augusta - Closed Project MPO and FS\Augusta Resource - Reclamation\5.0 Reports-Deliverables\5.2 Final Reports\Figures (Cadd)\REVISION C\FIGURE 31.dwg SAVED: 1/31/08 PRINTED: 3/11/08 BY: LENOVO USER



Prepared by:  
**M3** Engineering & Technology Corp.  
Tucson, Arizona  
Tel. (520) 293-1488 Fax. (520) 293-8349  
Hermosillo, Sonora Mexico  
Tel. 011-52-622-2105400  
Fax. 011-52-622-2105404

Issued by:  
**TETRA TECH**  
3031 West Ina Road  
Tucson, Arizona 85741  
(520) 297-7723 (520) 297-7724 fax

<b>RECLAMATION AND CLOSURE PLAN POST-MINING AND FACILITY RENDERED VIEW W/ RELIEF FROM MILEPOST 44</b>			 REVISION
Project: ROSEMONT COPPER	Project no.: 320614	Figure no.: <b>31</b>	
Location: PIMA COUNTY, ARIZONA	Date: 01/08		